


Meeting 2 9/3

Tuesday, September 03, 2013 7:35 PM




Power Supplies

- UPS -- Web-based Q/As (reliability)
- Wind Power Generator
 - DC power => Op-Ckt, +/- DC 12V to 20V
 - 3.7V Battery; 9V =>





DC-DC Converter

Step up
Step down



120V 1/3 hp 3A
Relay
SSR



— 500 —

Relay

